

# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer Devi E
2. Name of the School Jai Matha Public School
3. Location with name of Education District/ Sub. District Sahayagiri Marayoor, Idukki
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.  
618.66 m<sup>2</sup> GF, RCC  
661.08 m<sup>2</sup> - FF, RCC  
648.79 m<sup>2</sup> - SF, RCC  
648.79 m<sup>2</sup> - TF, GI Sheet
5. Period for which the certificate is issued 2021-2022
6. Nature of defects, if any  
a) Foundation and basement  
b) Superstructure  
c) Doors and Windows  
d) Wood work wrought and put up  
e) Roof  
f) Flooring  
g) Miscellaneous (Cracks, etc.)  
Nil.
7. Any major defects noticed which will render the building unsafe in any manner  
Nil
8. Whether maintenance works have been done properly Yes
9. Whether the structure is sound or not for conducting classes Sound under normal weather conditions.

**Note :** 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE

certified that the school building was inspected by me on 25/05/2021 and found to be fit / unfit to conduct classes, for the period 2021 - 2022 for the reasons stated above.

Place: Marayoor  
Date: 25/06/2021



Devi E  
ASSISTANT ENGINEER  
I.S.G.D SECTION  
MARAYOOR.